## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U. S. Patent: 7,231,180 B2 Examiner: Sonny Trinh

Issued: June 12, 2007 Group: 2618

Inventor(s): Benson et al. Docket No. H0005313

For: AIRCRAFT ENGINE SENSOR NETWORK USING

WIRELESS SENSOR COMMUNICATION MODULES

## **CERTIFICATE OF CORRECTION UNDER 37 CFR 1.322**

Attn: Certificate of Corrections Branch

P.O. Box 1450

Alexandria, VA 22313-1450

Sir:

Please correct the above-identified patent by issuing a Certificate of Correction for a Patent Office mistake under Rule 1.322 as follows:

Column 13, line 19, "convener" should be changed to --converter--; Column 14, line 54, "thereof to" should be changed to --thereof, to--.

These errors occurred through the fault of the Patent Office and no fee is involved. The issuance of a Certificate of Correction under Rule 1.322 is therefore considered proper.

Respectfully submitted,

Date: August 10, 2007 /PAUL D. AMROZOWICZ, REG. # 45264/

Ingrassia Fisher & Lorenz, P.C. By: Paul D. Amrozowicz

Attorney for Applicant(s) Tel. (480) 385-5060